

10/761833

  
PATENT

DOCKET NO.: 2004.01.008.WS1

CLIENT NO.: SAMS01-00327

Customer No.: 23990



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent No. : 6,956,896 B2  
Inventor(s) : Mitchell K. Johnson  
Issued : October 18, 2005  
Title : HIGH ACCURACY RECEIVER FORWARD AND REFLECTED PATH  
TEST INJECTION CIRCUIT

Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

CERTIFICATE OF MAILING BY FIRST CLASS MAIL

Sir:

The undersigned hereby certifies that the following documents:

1. Request for Certificate of Correction (in duplicate);
2. Certificate of Correction (in duplicate); and
3. A postcard receipt

Certificate  
MAY 10 2006  
of Correction

relating to the above application, were deposited as "First Class Mail" with the United States Postal Service, addressed to Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on May 4, 2006.

Date: May 4, 2006

Kathy Hamilton  
Mailer

Date: May 4, 2006

William A. Munck  
William A. Munck  
Reg. No. 39,308

P.O. Drawer 800889  
Dallas, Texas 75380  
Phone: (972) 628-3600  
Fax: (972) 628-3616  
E-mail: [wmunck@munckbutrus.com](mailto:wmunck@munckbutrus.com)


MAY 10 2006

DOCKET NO.: 2004.01.008.WS1

PATENT

CLIENT NO.: SAMS01-00327

Customer No.: 23990



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent No. : 6,956,896 B2  
Inventor(s) : Mitchell K. Johnson  
Issued : October 18, 2005  
Title : HIGH ACCURACY RECEIVER FORWARD AND REFLECTED  
PATH TEST INJECTION CIRCUIT

Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:

**REQUEST FOR CERTIFICATE OF CORRECTION**

Certain clerical or typographical errors were noted in the above-identified patent as indicated on the attached Certificate of Correction.


Applicant respectfully requests that a Certificate of Correction be issued pursuant to 37 C.F.R. §1.322. It is believed that this error is the office's mistake and therefore no fee is due. If this is incorrect, the Commissioner is hereby authorized to charge any additional fee associated with this communication or credit any overpayment to Deposit Account Number 50-0208.

MAY 10 2006

Respectfully submitted,

MUNCK BUTRUS, P.C.

Date: May 4, 2006

  
\_\_\_\_\_  
William A. Munck  
Registration No. 39,308

P.O. Drawer 800889  
Dallas, Texas 75380  
Telephone: (972) 628-3600  
Facsimile: (972) 628-3616  
E-mail: [wmunck@davismunck.com](mailto:wmunck@davismunck.com)

MAY 10 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

PATENT NO. : 6,956,896 B2

DATED : October 18, 2005

INVENTOR(S) : Mitchell K. Johnson

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 65, delete "ES" and replace with --BS--;

Column 9, line 16, delete "." after the term "controller";

Column 12, line 7, delete "." after the term "resultant";

Column 12, claim 1, line 23, delete "(RE)" and replace with --(RF)--.

**MAILING ADDRESS OF SENDER:**

Docket Clerk  
P.O. Drawer 800889  
Dallas, Texas 75380

PATENT NO. 6,956,896 B2

No. of additional copies

 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*

**MAY 10 2006**

DOCKET NO.: 2004.01.008.WS1

PATENT

CLIENT NO.: SAMS01-00327

Customer No.: 23990



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent No. : 6,956,896 B2  
Inventor(s) : Mitchell K. Johnson  
Issued : October 18, 2005  
Title : HIGH ACCURACY RECEIVER FORWARD AND REFLECTED  
PATH TEST INJECTION CIRCUIT

Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:

**REQUEST FOR CERTIFICATE OF CORRECTION**

Certain clerical or typographical errors were noted in the above-identified patent as indicated on the attached Certificate of Correction.

Applicant respectfully requests that a Certificate of Correction be issued pursuant to 37 C.F.R. §1.322. It is believed that this error is the office's mistake and therefore no fee is due. If this is incorrect, the Commissioner is hereby authorized to charge any additional fee associated with this communication or credit any overpayment to Deposit Account Number 50-0208.

MAY 10 2006

Respectfully submitted,

MUNCK BUTRUS, P.C.

Date: May 4, 2006



William A. Munck

Registration No. 39,308

P.O. Drawer 800889  
Dallas, Texas 75380  
Telephone: (972) 628-3600  
Facsimile: (972) 628-3616  
E-mail: [wmunck@davismunck.com](mailto:wmunck@davismunck.com)

MAY 10 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

PATENT NO. : 6,956,896 B2  
DATED : October 18, 2005  
INVENTOR(S) : Mitchell K. Johnson

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 65, delete "ES" and replace with --BS--;  
Column 9, line 16, delete "." after the term "controller";  
Column 12, line 7, delete "." after the term "resultant";  
Column 12, claim 1, line 23, delete "(RE)" and replace with --(RF)--.

**MAILING ADDRESS OF SENDER:**

Docket Clerk  
P.O. Drawer 800889  
Dallas, Texas 75380

**PATENT NO. 6,956,896 B2**

No. of additional copies

 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*

**MAY 10 2006**